



Photo - Circa 1895



Photo - 2024



Stabilization Tasks









Stabilization Tasks




Fisher Mansion









Stabilization & Seismic Repairs

Seismic Repair Tasks

| DAMAGE TYPE | DISCIPLINE | TYPE OF DAMAGE | DAMAGE | NOTES |
|-------------|------------|----------------|---|---|
| 001 | Arch | Stabilization | Historic Brick Masonry Repair | Replace cracked masonry with salvaged brick to match existing. |
| 003 | Arch | Seismic | Historic Brick Masonry Repair | Remove horizontal lines of mortar joint 2" deep and install stainless steel helical bars into the brickwork. Inject epoxy consolident into larger cracks. Repoint with mortar to match existing. Replace cracked masonry. |
| 04 | Arch | Seismic | Historic Stone Masonry Repair | Replace stone with stone from similar geologic strata to match existing. |
| 06 | Arch | | Repoint Masonry | |
| 07 | Arch | Seismic | Reconstruct Chimney | Use salvaged brick and brick salvaged on site prior to earthquake. |
| 808 | Arch | | Remove And Replace, Railing And Stairs | Remove and replace temporary railing and refinish stairs |
| 009 | Arch | Seismic | Repair/Reattach Fire Egress Stair | Straighten bent members. Replace damaged members as required. Replace existing anchors with screened epoxy anchors. Anchor landing to wall with new screened epoxy anchors. Refinish stair. |
| 10 | Arch | Seismic | Interior painting | Paint all plaster in rooms with crack damage including ceiling. Color to match existing room, Architect to approve color |
| 11 | Arch | Stabilization | Refinish Metal Surface | |
| 12 | Arch | | Infill Annular Space | Reference repoint brick and stone masonry. |
| 13 | Arch | | Refinish Painted Surface | |
|)14 | Arch | | Consolidate Sandstone | Test consolidate in areas not visible on the exterior. Possible testing locations: Basement or under porch. |
| 016 | Arch | Stabilization | Temporarily Cover Openings in Soffit | Cover opening/damaged soffits with 3/4" plywood. Attach using 11/2" bugle head course thread screws, 6" O.C. to deter pest infiltration. |
| 017 | Arch | Stabilization | Patch and Repair Skylight | Replace Damaged structure. Refinish corroded structure. Replace broken lites of glass (Match existing). Remove and replace all sealant and flashing. Make watertight. Apply consolident c wood skylight support structure in areas of dry rot and refinish. |
| 18 | Arch | Stabilization: | Replace Roof-Match Existing | Remove and replace the roof with asphalt shingle and continous bituminous vapor retarder barrier |
| 19 | Arch | Stabilization | Repair/Replace Roof Drain Down Spout | Repair decorative roof drain down spout & connect to dry sump. Match original material, design and finish. |
| 23 | Arch | Stabilization | Remove and Replace Joint Sealant | |
| 24 | Arch | Seismic | Repoint Historic Masonry | Remove deteriorated mortar by hand raking the joints, avoid damaging masonry. Match existing mortar. Color. Aggregate Ratio, Compressive Strength & Flexural Bond Strength. |
| 31 | Arch | Seismic | Plaster Crack - Level 1 | Hairline cracking, 0.45mm or less. |
| 32 | Arch | Seismic | Plaster Crack - Level 2 | Cracking larger than level I and plaster has separated 6" on both sides of crack from substrate. |
| 33 | Arch | Seismic | Plaster Crack - Level 3 | Plaster damage where sections of plaster have become detached. |
| 34 | Arch | Seismic | Plaster Crack - Level 4 | Plaster damage where sections of plaster have become detached and the masonry or substrate is damage behind plaster and requires stitching or replacement |
| 37 | Arch | | Plaster Crack - Level 3 | Plaster damage where sections of plaster have become detached |
| 38 | Arch | | Plaster Crack - Level 4 | Plaster damage where sections of plaster have become detached and the masonry or substrate is damage behind plaster and requires stitching or replacement |
| 55 | Arch | Stabilization | Non-Damaging Window Protection | Seal windows by non-destructive means: Press fit 2x4 wood subframe with perimeter backer rod seal. Do not anchor/damage sills, jambs headers or window frames. Attach 3/4" plywood subframe. Prime and paint exterior of plywood with latex paint. |
| 59 | Arch | Seismic | Plaster Crack - Level 1 | Hairline spider cracking, 0.45mm or less: |
| 00 | Civil | | Replace Sewer Line | Replace collapsed sewer line from the main line on the West of the property to both connections on the North West and North East connections to the mansion. |
|)1 | Civil | | Install Dry Wells | Install 3 roof water dry wells, 16' from mansion. |
| 00 | Struct | Stabilization | Roof To Wall Connection Upgrades | Install new blocking between joists, bond beams, anchors, and roof nailing to positively anchor roof to walls |
| 01 | Struct | Stabilization | Roof Framing Upgrades | Strengthen deficient roof joists and connections to supporting members |
| 02 | Struct | | Floor To Wall Connection Upgrades | Install new blocking between joists, anchors, and nailing to positively anchor floor to walls. |
| 03 | Struct | | Floor Joist Upgrades | Strengthen floor joists that are required to transfer gravity loads at each level where bearing walls do not line up vertically. |
| 04 | Struct | Stabilization | Masonry Wall Center-Core | Install reinforcing and grout in vertical cores at/near center of brick masonry walls. Cores extend from roof to foundation level. |
| 05 | Struct | | Floor Joist and Sheathing Repairs | Repair damaged and deteriorated floor joists |
| 59 | Struct | | Replace All Sub-floor | Remove all flooring and sub-floor and replace. |
| 1 | Struct | | Reinforce Both Sides of Foundation Wall | Place single-formed wall on exterior of foundation and shotcrete on the interior with reinforcement. Prime and paint all interior surfaces. |
| 00 | Mech | | Replace Basement Furnaces | Replace both existing furnaces. |
| 501 | Mech | | Upstairs Furnace | Existing upstairs furnace is to remain. Perform a full maintenance routine for the existing furnace, evaporator coil, and condensate drain line. Verify the functionality of the system including controls. Field verify exact condenser size and refrigerant type to match existing coil. Cover condenser pipe with insulation and 22ga, brake metal cover, include welded wire security cage. Prime and paint to match existing sheet metal. Add landscaping to screen. |
| 303 | Mech | Stabilization | Remove HVAC Window Unit | Remove window unit. Infill opening with temporary plywood. Remove all electrical back to outlet/panel. Remove all plumbing back to line connection. Cap connection. |
| 105 | Electrical | Stabilization | Demo old wiring | Disconnect old knob and tube wiring to any and all panels and devices. Demolish all other existing two wire or older wire systems to ensure building is up to code |
| 501 | Plumbing | Stabilization | Cap Sewer Openings | Cas/plug all abandoned sever openings in the building. |

41 Total Tasks

- 30 Stabilization Tasks
- 11 Seismic Repairs




41 Total Tasks

- 30 Stabilization Tasks
- 11 Seismic Repairs

Stabilization - Civil

- Reinstall Sewer
- Restore Down Spouts
- Connect Down Spouts to Dry Wells



41 Total Tasks


- 30 Stabilization Tasks
- 11 Seismic Repairs

Stabilization - Civil

- Reinstall Sewer
- Restore Down Spouts
- Connect Down Spouts to Dry Wells

Stabilization - Structural

Center Core the URM Walls, Add Grout and Rebar



41 Total Tasks


- 30 Stabilization Tasks
- 11 Seismic Repairs

Stabilization - Civil

- Reinstall Sewer
- Restore Down Spouts
- Connect Down Spouts to Dry Wells

Stabilization - Structural

- Center Core URM Walls, Add Grout and Rebar
- Add New Roof Sheathing
- Connect Roof to Structure
- Connect Floor Plates to Exterior Walls
- Encapsulate Rubble Foundation with Reinforced Concrete and Through-bolts



SIMPSON HELI-TIE
INSERTED INTO MORTAR
JOINT AT STAIR STEP
CRACK. ROUT OUT MORTAR
AND INSTALL HELI-TIE 2"
INTO JOINT - REPOINT JOINT
AFTER INSTALLATION

CRACK REPAIR DETAIL

SCALE: NONE

(16 S-801)

Stabilization & Seismic Repairs

Stabilization - Structural

 Stitch Cracks in Brick and Stone with Helical Ties and Grout


- Cio •

Stabilization & Seismic Repairs

Stabilization - Structural

- Stitch Cracks in Brick and Stone with Helical Ties and Grout
- Replace Plank Subfloor with Plywood Sheathing

SLOPE




Stabilization & Seismic Repairs

Stabilization - Structural

- Stitch Cracks in Brick and Stone with Helical Ties and Grout
- Replace Plat Subfloor with Plywood Sheathing

Stabilization - Envelope

- Replace Roof and Gutters
- Repair Skylight




Stabilization - Structural


- Stitch Cracks in Brick and Stone with Helical Ties and Grout
- Replace Plat Subfloor with Plywood Sheathing

Stabilization - Envelope

- Replace Roof and Gutters
- Repair Skylight
- Replace and Reinforce Chimneys



Each Stabilization and Seismic Repair Tasks Are Identified



Each Stabilization and Seismic Repair Tasks Are Identified









Fisher Mansion - Stabilization

Each Stabilization and Seismic Repair Tasks Are Photographed









Fisher Mansion - Stabilization

Each Stabilization and Seismic Repair Tasks Are Photographed

| ROOM | | | | | | | | | | | | | |
|---------------------|-------------|--------|--------|--------|--------------|-------------------------|---|-------|----------|---------|--|--|--|
| 102 ITEM# | AREFI | | | | | | | | | | | | |
| | TYPE | LDC | ELEV | PHOTO# | RMa | | DAMAGE LOCATION | NOTES | UNIT DTY | UNITS | | | |
| 4/ALSUSB | 30.52 | - N | - 0 - | 2533 | - 102 | Plaster Crack - Level 2 | Vertical crack nearby by the freplace cove area. | 50 | CS | Sc.Ft. | | | |
| V/1=1203C | 3032 | IN. | 0 | 3542 | - 02 | Plaster Chack - Level 2 | Vertical crack of too right of hard window | 10 | 13- | SOF | | | |
| VAESC3c | 3032 | - IN: | - C - | 3542 | + 302 | Planter Crack - Level 2 | Vertical crack at teo-left of right window. | 10 | 2 | SalPt. | | | |
| VAE5059 | 1032 | - N | | 30/9 | - 102 | Waster Crack - Level 2 | Crack nearby the fire sprinkler pide | 10 | 0.5 | So.F.L | | | |
| VAE5030 | 2032 | N. | 1 6 | 3575 | 102 | Plaster Drack: Level 7 | Topy of the door hare | - 80 | 2 | Se.F. | | | |
| 74E 5035 | 032 | - N - | - 1 | 3576 | -102 | Plaster Crack - Level 1 | Top of the door frame | - 50 | 2 | 50 Ft. | | | |
| A-5034 | 1032 | N. | 1 2 1 | X575 | -102 | Righer Chick - Legal 2 | Soulariteful af the oppringrate | 10 | 9 | Sc.F. | | | |
| VAFSC35 | 1010 | - IN | E. | 3554 | 102 | Plaster Crock - Level 2 | Upper right corner of open head | - 60 | | Sc.Fr. | | | |
| VALSOIA | 1032 | - N | | 2654 | - 102 | Plastor Crack - Level 2 | Upper off correr of oper year | - 6 | 4 | So Ft. | | | |
| MARKO SA | 1032 | - N | 1 2 1 | 5567 | -102 | Plaster Crass - Level 2 | Cradit be ween lower and door frame | - 50 | 4 | Sc.F. | | | |
| 2/415055 | 1032 | N | N - | 3560 | - 102 | Plaster Crack - Level 2 | Crack at VW wall come: | -8 | 0.5 | SOFT. | | | |
| CIFA ENCIS | 032 | - N | . 5 . | 5525 | - 102 | Plaster Crack - Level 2 | undernosth bay window | 5 | 05 | Self t. | | | |
| IVAESOS | 032 | 10 | 3 | 3523 | 102 | Plaster Crack Level 2 | undernath by window | - 6 | 0.5 | SOF | | | |
| D/AC503 | 1032 | - 14 | - 3 | 3523 | - 102 | Plaster Crack - Level 2 | Settom left of bay window | - 66 | 0.5 | Sc.Ft. | | | |
| //4E503 | 10.62 | N N | 3 1 | 35.51 | - 102 | Planter Crack - Level 2 | SW Corner | 10 | M. S. | SQF1 | | | |
| R/AESOS | 1032 | N N | 3 | 3503 | 102 | Righter Chick Level 2 | Notice rate of buy window | 12 | 0.5 | SciFi. | | | |
| B/ALSCS | 552 | - N | - 3 - | 3323 | - 102 | Plaster Crack - Level 2 | Section right of bay window | - 84 | 0.5 | Sc.P. | | | |
| IVAE 6035 | 1000 | N | W | 5329 | 62 | Planter Crack - Level 2 | Small chack at SW wall come nearby baseboard | - 6 | 4.2 | Sc.F. | | | |
| 2/A=503b | 1032 | | 9/ | 3529 | 102 | | | - 12 | - | So.Ft. | | | |
| | | IN. | | | | Planter Crass - Level 2 | Har Zontal-arack above baseboard | - 10 | | | | | |
| 5/AC503# | C12 C12 | - IN | - 97 - | 5541 | - 102 | Plastor Clack - Lovel 2 | crack at bottom right of window next to coor. | - 10 | C.E. | Soft. | | | |
| 6//E503a | 1052 | IN. | 90 | 3541 | 102 | Plaster Chack Level 2 | orack at bottom left of windownext to freologe | - 12 | 0.5 | ScaF1. | | | |
| 7/AE503b | 032 | N. | - 97 | 3338 | - 102 | Planter Crack - Level 2 | Crack at freplace way corner | 10 | 1 | 50.Ft. | | | |
| 5/AE503b | 50.52 | - N | - 97 - | 3548 | - 02 | Plaster Crack - Level 2 | Vertical crack between freplace and stridosy | į¢. | 5 | Sc#t. | | | |
| VA-503b | 1032 | 114 | 90 | 3572 | 102 | Plaster Cratic Level 2 | Crack at poteon light of window frame | 10 | 0.5 | SOF: | | | |
| 5/AE5C35 | (032 | - IN | - W - | 3529 | + 102 | Planter Crack - Level 2 | Crack at bottom of single frame | 10 | 0.5 | 58.Pt. | | | |
| (/AE505b) | 0.52 | - N | 97 | 3029 | 102 | Plaster Crack - Level 2 | Crack at cotton reft of window frame | [0 | 2 | So.F.L | | | |
| N/AFSCR5 | 2032 | N. | W | 3529 | 102 | Photer Crack in evel 2 | Small crack at 5W wall corper nearby baseboard | - 30 | 0.5 | SWET. | | | |
| VALSO3c | 1022 | - N | - C - | 3388 | - 102 | Plaster Crack - Level 5 | uong horizontal crack though the window bay colling | - 50 | 8 | 50 Ft. | | | |
| 15/AE503E | C55 | - IN | - C | 3588 | - 702 | Master Crack - Level & | Hor world grack above the window | 10 | 4 | Sc.F. | | | |
| E/AF5036 | 1023 | - IN - | - 0 | 3588 | -1102 | Planter Crock - Level 3 | Hor won't drack if SW calling portrar | 10 | 3 | Sc.Ft. | | | |
| 2/AC508c | 1033 | - 14 | - 2 - | 3588 | - 302 | Plaster Crack - Level 3 | Vertical crack at NE colling corner | 10 | 2 | Saft | | | |
| S/AES03c | 033 | - N | - C - | 2305 | -1102 | Plaster Crack - Level 3 | Crack at top left of left window | 0 | 3 | SqFt | | | |
| 6/AE503c | 1033 | - 24 | - 0 - | 2305 | -1102 | Plaster Crack - Level 5 | crack nearby fireplace | 10 | 9 | SaFt | | | |
| 7/AE503c | 1033 | - IN | - C | 3728 | -102 | Plaster Crack - Level 3 | Honzontal crack at North ceiling cove, at right | 0 | 10 | Sq.Ft. | | | |
| 8/AE503c | 1033 | - IN | - C | 3728 | -1102 | Plaster Crack - Level 3 | Horizontal crack at North ceiling cove, at left | 10 | 6 | SqFt | | | |
| 17AE503a | 033 | - IN | - 10 | 3563 | -1100 | Plaster Crack - Level 3 | Vertical crack at NE wall corner | 0 | 10 | SaFt | | | |
| VAE503a | 033 | 24 | - 5 | 3297 | -102 -102 | Planter Crack - Level 3 | SE CORNER | 0 | 12 | SaFt | | | |
| IO/AE503a | 036 | - 24 | . F | 3565 | -19052 | Plaster Crack - Level 2 | Vertical crack nearby NE wall corner | 0 | 13 | Sage | | | |
| 8/AE503a | 036 | - 24 | 1 2 1 | 3564 | 102 | Plaster Crack - Level 2 | horzontal damage cross the wall light. | 0 | Til. | SqFt. | | | |
| 10/AES03c | 036 | 24 | 3 1 | 3523 | -1102 | Plaster Crack - Level 2 | Left bay window edge | 0 | 10 | SoFt | | | |
| VAESOS: | 036 | - 24 | - 5 | 3523 | -102 | Planter Crack - Level 2 | Right bay window edge | ő | 10 | 50FE | | | |
| /AE503b | 036 | - 24 | - W | 3541 | -102 | Plaster Crack - Level 2 | Crack at base board | 0 | M | 50.Ft | | | |
| 0/AE503b | 036 | - IN | - W | 1529 | -102 | Plaster Crack - Level 2 | Itwo small horizontal damage | lo lo | 17 | Saft | | | |
| S/AF503a | 1036 | - N | W | 3541 | -102 | Plaster Crack - Level 2 | Crack around window next to the door | 10 | 25.5 | Supt | | | |
| 4/AF505a | 036 | - 24 | W | 3541 | -102 | Master Crack - Level 2 | Crack around window next to the freplace | 0 | 23 | SaFt | | | |
| M/AESUSE MAESUSE | 1036 | 74 | W | 3541 | 102 | Playter Crack - Level 2 | Crack around window next to the freplace | M | 25 | SQF. | | | |
| VAESC35 | 1036 | N N | - W - | 3509 | + 102 | Plaster Crack - Level 2 | | -6 | 6 | St.Ft. | | | |
| CAL SUS | | | | | | | horizontal damage cross the well lights | ly. | 0 | | | | |
| T/AE503c | 037 | - N | - 5 | 3623 | - 102 | Master Crack - Level 3 | Water camage underneath bay window | 19 | | Soft | | | |
| NAF50RE | F0162 | N N | 1.6 | 7.737 | 102 | Mixter Crock - evel 1 | Solder crack on entire delling | | 460 | SOLET, | | | |










032-IN-S-3523-102



032-IN-S-3523-102







GSBS

AE503

Stabilization & Seismic Repairs

Each Stabilization and Seismic Repair Tasks Are Photographed, Identified Dimensioned & Scheduled










032-IN-C-7046-104
































GSBS -





NOTE - THIS SHEET IS INTENDED TO BE VIEWED IN COLOR




FISHER MANSION STABILIZATION

SALT LAKE CITY CONFERENCE CONFORMATION


CAN DATE OF THE CONFORMATI


AE505






SUSPENDED REFRIGERANT PIPE SUPPORT AT TRUSS DETAIL







REFRIGERANT PIPE SUPPORT ON ROOF DETAIL




REFRIGERANT PIPE VERTICAL SUPPORT DETAIL






DUCT CONSTRUCTION DETAIL.



FURNACE DETAIL





Stabilization & Seismic Repairs

Mechanical Stabilization

- Add a Condenser for Attic Furnace
- Replace Basement Furnaces
 - Mechanical Upgrades to Temper Interior Conditions for Historic Millwork, Plaster and Fire Sprinklers



Thank you, Friends of Fisher Mansion!

 Your support helps keep the stories alive and the mansion standing strong for future generations